# Maintenance Plan SLK Multy Product Family





### Wellell Group

SLK Vertriebsgesellschaft mbH Am Herdicksbach 18 D-45731 Waltrop

Telefon: +49 (0) 2309 - 91545 - 0 Telefax: +49 (0) 2309 - 91545 - 999 E-Mail: info@slk-gmbh.de Internet: www.slk-gmbh.de



#### Please use the current maintenance plan from the SLK website www.slk-gmbh.de (download area) for documentation.

Pos.		Object	ОК	not OK	Remarks	Repaired on:
1	Hoist in original con	dition				
2	Compatibility certificate for accessory and device combinations is available					
3	User guide available	2				
4	Type labels present	and legible				
5	Casters	• turn easily				
		• pivotable by 360°				
		• undamaged				
		• Fastening screws tightened firmly				
		• Brakes in functional condition				
		• Base				
	Welding seams	• Mast				
	Welding seams ok/ no crack formations/ no deformations	<ul> <li>Lifting arm (also notice long hole formation on the CSP)</li> </ul>				
6		• Pusher bar				
		Motor brackets				
		<ul> <li>Spreader bar/footboard/shin support (depending on model)</li> </ul>				
7	No surface damage or corrosion					
8	Function of the base expansion works easily					
9	Bolt with SL clip in proper condition (replace in case if marks are present)					
10	Bolt for fixating the lifting arm (40mm long) and the mast (60 mm long) are present and in proper condition (replace in case marks are present)					
11	Screws tightened firmly	<ul> <li>between the base and mast</li> </ul>				
		<ul> <li>between the mast and lifting arm (100 Nm tightening torque)</li> </ul>				
		<ul> <li>between the base and feet (100 Nm tightening torque)</li> </ul>				
12	Hoist bolt with collar for the spreader bar has a collar height of min. 4 mm. Double check the measurement with a slider gauge and enter it under "Remarks" (only <b>SLK Multy Universal</b> )					
13	Teflon washer is present between the hoist bolt and the spreader bar, min. 1 mm thickness or replace otherwise					

SWF

#### Serial number : \_\_ \_\_ \_\_ \_\_ \_\_ \_\_ \_\_ \_\_ \_\_ \_\_ \_\_

POS.	Object		ок	not OK	Remarks	Repaired on:	
14	Gas pressure spring is functional						
15	Folding mechanism is functional						
16	Pusher bar is screwed on						
17	Plug on the spreader bar is present/spring locks present on spreader bar (if applicable)	and plugs					
Electr	ical system						
18	All cables undamaged and connected						
19	Emergency-stop button present and functional (no fun emergency-stop button is pressed, reactivation only b						
20	Charger is present and undamaged, Connections clea orange control lamp during charging	IN,					
21	Charging function available						
22	No lift function during charging						
23	Tipping operation of the hand control works (releasing the hand control stops the lift operation)						
24	must be disabled						
25	Hand control including cable and strain relief are undamaged, control lamps work (if present)						
26	Seal ring present on the plug of the hand control						
27	Control box screwed on tightly						
28	Battery pack without external damage or deformation, Connections clean, locking of the battery pack engages						
29	Electrical control by means of the buttons on the control box works						
30	Indicators/displays function						
31	Both limit switches function (drive switches off at the top and bottom)						
32	2 No remarkable noises in the drive motor						
33	Mechanical emergency lowering works						
34	Grease deposits removed from the thrust rod						
35	Electrical base expansion works (if present)						
36	Test of the entire lifting cycle pursuant to EN 10535 Annex B1 Multy Universal: with maximum nominal load of the hoist Multy Aktiv: with 50% of the maximum nominal load of the hoist						
	The patient hoist can be used.						
The patient hoist must be serviced before reuse.							
	A corresponding label has been appended. The person responsible has been informed and						
	hereby confirms this with their signature:						
Positior	) of the responsible person:	Name in prir	nted le	tters:			
Date:	Date: Sic		Signature of tester:				

Next servicing:	
9	

\_\_\_\_

Maintenance Plan SLK Multy Product Family\_EN

## All defects have been repaired professionally. The patient hoist can be used.

\_\_\_\_

Date.
-------

Next servicing:

Name in printed letters:

Name in printed letters:

LI-WP-102	rev 002

25.02.2024